HABS No. NJ-982-B

BOTANY WORSTED MILLS, BAG FACTORY 176 Parker Avenue Passaic Passaic County New Jersey

HABS NJ, 16-PASA, 7-B-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

HABS NJ, 16-PASA, 7-B-

HISTORIC AMERICAN BUILDINGS SURVEY

BOTANY WORSTED MILLS, BAG FACTORY

HABS No. NJ-982-B

Location:

176 Parker Avenue, Passaic, Passaic County, New

Jersey

USGS Weehawken, New Jersey Quadrangle Universal Transverse Mercator Coordinates:

18.574000.4524700

Significance:

Constructed as a bag factory, the building was

originally part of Botany Worsted Mills, founded

in 1889 as the first integrated woolen processing plant in the United States.

Description:

The one-story, five-bay frame building facing Parker Avenue has a shallow gable roof covered in asphalt shingle with a crudely bracketed cornice. The exterior of the building has been sheathed in corrugated metal, and the regularly spaced windows have been removed; covered openings are still visible on the interior. A round metal stack projects on the exterior of the eastern end of the structure. The interior features narrow horizontal tongue and groove walls stylistically consistent with the 1910-18

building are 45' x 120'.

History:

The buildings at 176 Parker Avenue were originally part of the Botany Worsted Mills complex, founded in 1889 as the first integrated woolen processing plant in the United States. Representing a later period in the development of the mill, the bag factory was built between 1910 and 1918. Botany Mills ceased production in 1955, after which the building was leased to a number of industrial tenants.

construction date. Overall dimensions of the

No specific documentary evidence was found regarding the building's historic function. Presumably, the bag factory manufactured cloth storage bags for unspun wool.

BOTANY WORSTED MILLS Bag Factory HABS No. NJ-982-B (page 2)

No material evidence, either mechanical or architectural, exists to explain the precise activities that took place within the building during its ownership by Botany Mills.

Sources:

Sanborn Insurance Maps, City of Passaic, 1910


and 1918

Historian:

Sally Milner, ACROTERION, 71 Maple Avenue,

Morristown, NJ, December 1989

BOTANY WORSTED MILLS Bag Factory HABS No. NJ-982-B (page 3)



= subject property
(not to scale)

